



Notice to Mariners

Rampion Offshore Wind Farm

Date of Issue: 04/12/2017

Notice Expires: Ongoing

Dear Authorities, Owners, Ships Agents, Masters, Pilots and Fishermen,

This notice closes out all previous notifications regarding Rampion cardinal and wave rider buoys

Wave Rider Buoys

Please note that Wave Rider Buoy No. 2 has now been relocated. New Wave rider locations are as follows:

ID	Latitude	Longitude	
Wave Rider No1	50°46.555'N	0°19.070'W	As Laid
Wave Rider No2	50°41.394'N	0°16.146'W	New coordinates
Wave Rider No3	50°40.219'N	0°12.949'W	As Laid

New Coordinates of wave rider 2 highlighted in yellow above.

The buoys are fitted with an amber flashing light, flashing 5 times at 0.5 Hz every 20 seconds

Cardinal Buoys

Cardinal Name	Light Signature	AP Latitude	AP Longitude	Deployed Latitude	Deployed Longitude	Approx Water Depth (LAT)
North 1	Q	50°41.375'N	0°21.901'W	50°41.377'N	0° 21.898'W	18m
North 2	V Q	50°42.072'N	0°17.095'W	50° 42.072'N	0° 17.098'W	22m
North 3	Q	50°42.769'N	0°12.284'W	50° 42.771'N	0° 12.286'W	23m
East 1	Q (3) 10s	50°41.051'N	0°11.310'W	50° 41.050'N	0° 11.311'W	30m
South 1	Q (6) + L Fl 15s	50°39.170'N	0°11.365'W	50° 39.172'N	0° 11.363'W	47m
South 2	V Q (6)+L Fl 10s	50°38.399'N	0°16.149'W	50° 38.398'N	0° 16. 147'W	42m
South 3	Q (6) + L Fl 15s	50°37.629'N	0°20.928'W	50° 37.631'N	0° 20.931'W	25m
West 1	Q (9) + 15s	50°39.439'N	0°21.931'W	50° 39.439'N	0° 21.930'W	30m

East 1 Cardinal top mark has been repaired



Notice to Mariners

Rampion Offshore Wind Farm

Date of Issue: 04/12/2017

Notice Expires: Ongoing

Mark Brown

Offshore Site Manager

Tel: +44 (0) 7491 057 121

Email: mark.brown@eon.com

Gordon Bain

Lead Marine Coordinator

Tel: +44 (0) 7816 648082

Email: leadmc@rampionoffshore.com

Duty Marine Coordinator

Tel: +44 (0) 7557 942945

Email: traffic@rampionoffshore.com

Alex Winrow-Giffin

Brown & May Fisheries Liaison

Tel: +44 (0) 7760 160039

Email: alex@brownmay.com