



Notice to Mariners

Rampion Offshore Wind Farm

Date of Issue: 15th December 2015

Notice Expires: Ongoing

Dear Authorities, Owners, Ships Agents, Masters, Pilots and Fishermen,

Re: Rampion Offshore Wind Farm - Deployment of new Project Cardinal Buoys (Construction Period)

Please be advised that the above stated Marks have all now been fully deployed in the following as laid positions.

Cardinal Name	Light Signature	AP Latitude	AP Longitude	Deployed Latitude	Deployed Longitude	Approx Water Depth (LAT)
North 1	Q	50°41.375'N	0°21.901'W	50°41.377'N	0° 21.898'W	18m
North 2	V Q	50°42.072'N	0°17.095'W	50° 42.072'N	0° 17.098'W	22m
North 3	Q	50°42.769'N	0°12.284'W	50° 42.771'N	0° 12.286'W	23m
East 1	Q (3) 10s	50°41.051'N	0°11.310'W	50° 41.050'N	0° 11.311'W	30m
South 1	Q (6) + L Fl 15s	50°39.170'N	0°11.365'W	50° 39.172'N	0° 11.363'W	47m
South 2	V Q (6)+L Fl 10s	50°38.399'N	0°16.149'W	50° 38.398'N	0° 16. 147'W	42m
South 3	Q (6) + L Fl 15s	50°37.629'N	0°20.928'W	50° 37.631'N	0° 20.931'W	25m
West 1	Q (9) + 15s	50°39.439'N	0°21.931'W	50° 39.439'N	0° 21.930'W	30m

NB-

The top Mark on South 1 was damaged on deployment, the mark is still intact and serviceable. This will be replaced as soon as practicable.

AIS not yet activated as the project is waiting for the OFFCOM licenses to be issued.



Sealite Atlantic 2600 Type 2
Cardinal Mark




Notice to Mariners

Rampion Offshore Wind Farm

Date of Issue: 15th December 2015

Notice Expires: Ongoing

Rampion Offshore Wind Farm Site Map



For Any Further details contact:-

Gordon Bain Eon Lead Marine Coordinator +44(0)7787 241442

Email- leadmc@rampionoffshore.com.

Rampion Duty Marine Coordinator +44(0)7557 942945

Email- traffic@rampionoffshore.com

David Guy (Fisheries Liaison) +44(0)7980 591631

Email- newhavenfish@gmail.com