



Notice to Mariners

Rampion Offshore Wind Farm

Date of Issue: 13/03/2018

Notice Expires: Ongoing

All Mariners,

Re: Rampion Offshore Wind Farm – Eon-NTM-0100 Service and Relocation of Wave Rider Buoys Update

Unfortunately, the intended vessel for above operations was not able to carry out the task. We are looking at alternative vessels and will update accordingly.

Please note the AToN on Wave rider 1 and 3 is extinguished.

Please find below coordinates for reference.

Buoy	Current Position				Re-deployed Position			
	Lat	Long	Easting	Northing	Lat	Long	Easting	Northing
#1 KP5	50°46.5548'N	0°19.0708'W	689097	5628336	50°46.5468'N	0°18.8644'W	689340	5628330
#2 EOS	50°41.3938'N	0°16.1463'W	692886	5618899	50°41.3938'N	0°16.1463'W	692886	5618899
#3 Array	50°40.2026'N	0°12.9500'W	696731	5616832	50°40.0593'N	0°12.1951'W	697630	5616600

Wave rider 1 and 3 will be relocated

Mark Brown

Offshore Site Manager

Tel: +44 (0) 7491 057 121

Email: mark.brown@eon.com

Gordon Bain

Lead Marine Coordinator

Tel: +44 (0) 7816 648082

Email: leadmc@rampionoffshore.com

Duty Marine Coordinator

Tel: +44 (0) 7557 942945

Email: traffic@rampionoffshore.com

Alex Winrow-Giffin

Brown & May Fisheries Liaison

Tel: +44 (0) 7760 160039

Email: alex@brownmay.com