



Notice to Mariners

Rampion Offshore Wind Farm

Date of Issue: 08/08/2017

Notice Expires: Ongoing

Dear Authorities, Owners, Ships Agents, Masters, Pilots and Fishermen,

Re: location of wave rider 3;

This notice closes out all previous notifications regarding Rampion wave rider buoys

Please note that Wave Rider Buoy No. 3 has now been relocated. New Wave rider locations are as follows:

ID	Latitude	Longitude	
Wave Rider No1	50°41.675'N	000°16.299'W	As Laid
Wave Rider No2	50°40.219'N	000°12.949'W	As Laid
Wave Rider No3	50° 46.555' N	000° 19.070' W	New coordinates

New Coordinates of wave rider 3 highlighted in yellow above.

The buoys are fitted with an amber flashing light, flashing 5 times at 0.5 Hz every 20 seconds

Marcus Moore

Offshore Site Manager

Tel: +44 (0) 7447 013684

Email: marcus.moore@rampionoffshore.com

Gordon Bain

Lead Marine Coordinator

Tel: +44 (0) 7816 648082

Email: leadmc@rampionoffshore.com

Duty Marine Coordinator

Tel: +44 (0) 7557 942945

Email: traffic@rampionoffshore.com

Alex Winrow-Giffin

Brown & May Fisheries Liaison

Tel: +44 (0) 7760 160039

Email: alex@brownmay.com