



# Notice to Mariners

## Rampion Offshore Wind Farm

Date of Issue: 02/12/2017

Notice Expires: Ongoing

Dear Authorities, Owners, Ships Agents, Masters, Pilots and Fishermen,

### Relocation of wave rider 2;

**This notice closes out all previous notifications regarding Rampion wave rider buoys**

Please note that Wave Rider Buoy No. 2 has now been relocated. New Wave rider locations are as follows:

ID	Latitude	Longitude	
Wave Rider No1	50°41.675'N	000°16.299'W	As Laid
Wave Rider No2	50°41.3940'N	0°16.1460'W	New coordinates
Wave Rider No3	50° 46.555' N	000° 19.070' W	As Laid

New Coordinates of wave rider 2 highlighted in yellow above.

The buoys are fitted with an amber flashing light, flashing 5 times at 0.5 Hz every 20 seconds

#### Gordon Bain

Lead Marine Coordinator

Tel: +44 (0) 7816 648082

Email: [leadmc@rampionoffshore.com](mailto:leadmc@rampionoffshore.com).

#### Duty Marine Coordinator

Tel: +44 (0) 7557 942945

Email: [traffic@rampionoffshore.com](mailto:traffic@rampionoffshore.com)

#### Alex Winrow-Giffin

Brown & May Fisheries Liaison

Tel: +44 (0) 7760 160039

Email: [alex@brownmay.com](mailto:alex@brownmay.com)